

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program February 15, 2007

Supervisor _



Permit number: S/039/019 Mine Name: Flower Patch Ouarry **Inspection Date:** February 14, 2007 Operator Name: Bown Stone Products, Inc. **Time:** 1:15 pm **Inspector(s):** Lynn Kunzler, DOGM Other Participants: none Mine Status: Active **Elements of Inspection** Evaluated Comment Enforcement 1. Permits, Revisions, Transfer, Bonds 2. Public Safety (shafts, adits, trash, signs, highwalls) 3. Protection of Drainages / Erosion Control 4. Deleterious Material 5. Roads (maintenance, surfacing, dust control, safety) 6. Concurrent Reclamation 7. Backfilling/Grading (trenches, pits, roads, highwalls, 8. Soils 9. Revegetation

Purpose of Inspection:

10. Other

Request from SITLA to inspect site while in area - SITLA had received complaint regarding this operation

Inspection Summary:

This Quarry was approved on July 20, 2006. Originally part of the Mayfield Quarry (S/039/011), the operator had been mining for. After a Cessation Order was issued for exceeding the 5-acre limit for a small mining operation, Bown Stone Products permitted the area outside the Mayfield Quarry boundary that they had disturbed. The site was active at the time of this inspection. During this inspection, it was noted that there was about 1/2 acre of additional disturbance from when the site was originally permitted, but this was still within the area outlined for the permit.

It was also noted during this inspection that trash, debris and potentially delitareous materials were cleaned up and/or properly stored. There were no erosional problems noted.

Photos were taken to document site conditions.

Conclusions and Recommendations:

This site appears to be in compliance at this time. It is recommended to continue to monitor this site when in the area.

Inspector's Signature

LK:pb

O:\M039-Sanpete\S0390019-FlowerPatchQuarry\Inspections\Insp-02142007.doc